

**Amendments to the Drawings:**

Replacement sheets 1, 3, and 5 submitted herewith contain the following amendments:

Sheet 1: Add reference 100 and arrow.

Add reference 107 and lead line.

Sheet 3: Extend the lead line for reference 350 to indicate a portion of the PCB 340 instead of a portion of the overmold section 352.

Complete the cross section hatching of the overmold section 352 above the lead 348.

Sheet 5: Change reference "500" pointing to the connector to "536".